SED301: further Reduced



SITE DESCRIPTION/EXECUTIVE SUMMARY

Site Name and Location

Eaton LDFL 1101 West Hanover Street Marshall, Michigan 49068 County:

Calhoun

Michigan Code Number:

None Jackson

DNR District:

EPA ID Number: MID006403349

1410005515929 SAS Score/Screen No.: None

This 5-acre landfill, owned and operated by Eaton Corporation, received limited industrial waste from 1969-1980. The waste material found on site included metal shavings, metal dust and water coolant metals. Also found were asbesto brick fire lining residue, a few barrels of the above materials, scraps of paper, and some containers filled with tar. In addition, Eaton Corporation reported in their CERCLA 103c notification of a hazardous waste site to EPA in 1981 of the presence of halogenated solvents and sludges in the landfill.

Because of the costs involved in meeting proposed state regulations, the landfill closed in 1980. No monitoring is occurring. The Kalamazoo River lies about 1500' to the south of the landfill.

Because of the potential hazard posed by this landfill from buried spend solvents and sludges, in addition to tar containers, and metals, further testing of the site is needed to determine the potential impact on the environment.

Recommendations for EPA

Sampling needs to be conducted in order to determine whether or not a release to the environment has occurred. This site receives a medium priority for inspection.

Pre-HRS Score: To be determined Projected HRS Score: To be determined SI Priority: Medium - State lead

Program Support Section

Hours Spent: Initial & Date: 2.0 10

Date of Previous Summary:

Previous Author:

Current Date: 11/9/87

Author: I. Ojong/B. Irish

Site Assessment Unit Environmental Response Division Michigan Dept. of Natural Resources

	POTENTIAL HAZAI	RDOUS WASTE SITE	I. IDENTIF	
SEPA	ASSESSMENT	31 STATE 01	7 1D 9055 15429	
	PART 1 - SITE INFORMA	TION AND ASSESSME	NT ZON	110-01313121
II. SITE NAME AND LOCATION				
O1 SITE NAME (Lagar, common or desembland name of site)			PECIFIC LOCATION IDENTIFIER	- C1
EATON LDFI		1101 h	HANDVE	R St
DARSHALL			CALHOUN	07COUNT 08 CONG COOE DIST 25 03
08 COORDINATES LATITUDE 42 16 10"	84°54'05"			
10 DIRECTIONS TO SITE Starting from rearest availe react	ansing-	HW 499/	275 to 1	Marshall
(about 80 miles),	To Site, take	- HW 12 to	HANOVE .	St.
III. RESPONSIBLE PARTIES				
01 OWNER (# smount)		02 STREET : Bionosa, Manny, res		
Eaton Corporat	(0 ^	1101 W	Hanover S	34
osan Marshall		04 STATE 05 ZIP CODE	OS TELEPHONE NUMBER	
		M 49068	() .	
07 OPERATOR IT areas and different from a		08 STREET (Brances, resure, res		1
Eaton Corpore	ation	1101 W	yanover	
Marshall Marshall		My 49068	12 TELEPHONE NUMBER	
13 TYPE OF OWNERSHIP (Choca one) A. PRIVATE B. FEDERAL				
,	Agenty name:	C. STATE		NICIPAL
☐ F OTHER:	Socier	C. G. UNKNK)WN	
14 OWNER/OPERATOR NOTIFICATION ON FILE (CAME)			AT 4	4 01
A. RCRA 3001 DATE RECEIVED WONTH	B UNCONTROL	LED WASTE SITE (CERCLA 103	DATE RECEIVED: 07 C	AV FAR I G. NONE
IV. CHARACTERIZATION OF POTENTIAL				
01 ON SITE INSPECTION WE YES DATE 11 73	BY (Chees of that apply) A EPA B B EP	A CONTRACTOR	STATE ID. OTHER	CONTRACTOR
T NO DATE MONTH DAY FEAR	C E. LOCAL HEALTH OFF	CIAL IF OTHER:	Specify	
	CONTRACTOR NAME(S):		394677)	
02 SITE STATUS (Check and)	03 YEARS OF OPER			
CA ACTIVE X B. INACTIVE CI C. UNI		1969 198		N
34 DESCRIPTION OF SUBSTANCES POSSIBLY PRESE				
halogenated sol	vents and sli	idges		
·		•		
			•	
os description of potential hazard to enviro Potential dama	ge to grou	indwater	and soil	
V. PRIORITY ASSESSMENT				
01 PRIORITY FOR INSPECTION (Chase and, if repr or mean	un la chaesas, comenno Pari 2 - Hispo sur	ITTUENDED AND PORT 3 - CONSTITUEN OF HOLE	retains Conditions and materials	
C A. HIGH C B. MEDII	UM C. LOW	D. NONE	er asition necessit, configures current dissoci	arton formi
VI. INFORMATION AVAILABLE FROM				
01 CONTACT	02 OF IApparaty Organ	range)		03 TELEPHONE NUMBER
Ron Keoistra	MD	NR		5171788-2598
04 PERSON RESPONSIBLE FOR ASSESSMENT	05 AGENCY	OS ORGANIZATION	07 TELEPHONE NUMBER	JS DATE
Roomdon wich I GNATIUS	DAUM PROLO	I I O N	(517) 272-4800	·

EPA PORM 2070-12 (7-81)
00930 PM

SEPA

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT

1. IDENTIFICATION

31 STATE 102 SITE NUMBER

26 MI DOD 55 1592 SI

1/61			PART 2 - WAST	e information	†	26 MIDOC	5515929
IL WASTES	TATES, QUANTITIES, AN	O CHARACTER	STICS			~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	
OI PHYSICAL S	TATES Cheer of the mater	OZ WASTE QUANT	TY AT SITE	OJ WASTE CHARACT	ERSTICS -chees as that a	200 1 .	
TA SOUG CA ROWOEL SC SLUGGE	I I G GAS		190	M A TOXIC III B CORRO III. C. RADIOA M D PERSIS	CTIVE OF GRUN	THOUS IT EXPLOS	VE /E ATIBLE
		100000		L			
IL WASTET			·		,		
CATEGORY	SUBSTANCE N		OI GAOSS AMOUNT	02 UNIT OF MEASURE			
(SLU)	SLUDGE	<u>r</u>			From 1969-1980, this 5-acre		
OFM	OILY WASTE				landfill reportedly received		
(sor)	SOLVENTS		190	cu.ft.	FOOL type waste (halogenated		
P90	PESTICIOES				solvents and sludges), as		
<u>∞cc</u>	OTHER ORGANIC CH			ļ.,	reported by the company in		
юc	INORGANIC CHEMIC	ALS			their CERCLA 103c		
ACD	ACIOS				notifical	ion to EPA	
BAS	BASES						
MES	HEAVY METALS		<u> </u>	ļ <u>.</u>	<u>L</u>		
	OUS SUBSTANCES			,		·	
OI CATEGORY	22 SUBSTANCE N	AME	03 CAS MUMBER	04 STORAGE/OIS	POSAL METHOD	05 CONCENTRATION	CONCENTRATION
	 						
				<u> </u>			
	 			SEE ABOV	E)		
				<u> </u>			
_			<u> </u>				
			T				
V SEEDETA	CX3 /See Against To CAS Pages		<u> </u>		 	<u> </u>	<u> </u>
						200 1111	44.44
CATEGORY	01 FEEDSTOC	K 74468	02 CAS NUMBER	CATEGORY	01 FEEDST	OCX MAME	02 CAS NUMBER
FOS			 	FOS			
FOS				FOS			
FOS				FOS			
F0 S		·	L	FOS			
VI. SOURCES	OF INFORMATION ICA	4944M - 1974MAR. 1 S.		ARRESTS /			
CE1 MD	ecla 103c onr Files	Notification	of Haz	bardons W	lesse Si	te	

SEPA

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT EXIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

I. IDENTIFICATION 26 MID 0055159 29

PART 3 DESCRIPTION OF THE	AZABOOS CONDITIONS AND INCIDENTS	
II. HAZARDOUS CONDITIONS AND INCIDENTS 01 & A GROUNDWATER CONTAMINATION 110	02 OBSERVED OATE	POTENTIAL C ALLEGED
32 BORN ATION BOTENTIALLY ASSECTED 1010 DT	34 NARRATIVE DESCRIPTION	
Potential Contamina	tion of ground h	rater in the
rovenius concamina	3 ().	
handful area		
01 %8 SURFACE WATER CONTAMINATION 10, 600	02 = OBSERVED (OATE.) 04 NARRATIVE DESCRIPTION	POTENTIAL
Potential contamina	thon of the kar	lamazoo.
River.	<u> </u>	
River.		
01 E.C. CONTAMINATION OF AIR	02 T OBSERVED (DATE.	T POTENTIAL TALLEGED
03 POPULATION POTENTIALLY AFFECTED	04 NARRATIVE DESCRIPTION	
NIA	·	
1.11.		
01 TO FIRE/EXPLOSIVE CONDITIONS	02 TOBSERVED (DATE.	_ POTENTIAL ALLEGED
03 POPULATION POTENTIALLY AFFECTED	04 NARRATIVE DESCRIPTION	:
, ,	بر	1
NA		:
01 I E. DIRECT CONTACT	02 TOBSERVED (DATE	T POTENTIAL TALLEGED
03 POPULATION POTENTIALLY AFFECTED	04 NARRATIVE DESCRIPTION	
.11.		
N/A		
, , , ,		
01 X F CONTAMINATION OF SOIL 5 QCHES	02 T OBSERVED (DATE	POTENTIAL ALLEGED
Ac/ 96)		
Potential Contamina	tion of sou in	the Landful
18 lemma Corraction	, 60	
		·
01 VG DRINKING WATER CONTAMINATION 03 POPULATION POTENTIALLY AFFECTED.	02 COBSERVED (DATE:)	#POTENTIAL ALLEGED
No residential well testing ha	s accurred in the area.	
No residential well testing "	Weeking in the same in	÷
* j. 36%	·	·
01 TH. WORKER EXPOSURE INJURY 03 WORKERS POTENTIALLY AFFECTED:	02 TOBSERVED (DATE: 1)	I POTENTIAL I ALLEGED
		•
.//^		
NJA	-	
OF VI COMILLATION EVENCEINE IN HIGH	02 T ORCEONED IOATE	POTENTIAL I ALLEGED
01 XI POPULATION EXPOSURE/INJURY 03 POPULATION POTENTIALLY AFFECTED:	02 T OBSERVED (DATE:) 04 NARRATIVE DESCRIPTION	APOTENTIAL I ALLEGED
	(dui king well) contami	on ben I
Through potential groundwater	Laria King well)	the same to
	•	

S.EPA

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT

I. IDENTIFICATION

PART'3 - DESCRIPTION OF	HAZARDOUS CONDITIONS AND INCID	ENTS 26 MIN 00 55 15929
IL HAZARDOUS CONDITIONS AND INCIDENTS Comment		
01 V J. DAMAGE TO FLORA 04 MARRATIVE DESCRIPTION	02 C OBSERVED IDATE.	,
Potential damage	to flora from	n damaged Soil.
01 T K DAMAGE TO FAUNA 04 NARRATIVE DESCRIPTION - Include name (s) of specimes	02 C OBSERVED (DATE:	_1 C POTENTIAL) C ALLEGED
01 T. L. CONTAMINATION OF FOOD CHAIN 04 NARRATIVE DESCRIPTION	02 C OBSERVED (DATE:	_ POTENTIAL _ ALLEGED
	NA	
01 3 M UNSTABLE CONTAINMENT OF WASTES Spot Annual Statement and Market Statement of Statement o	02 © OBSERVED (DATE:	_) C POTENTIAL _ ALLEGED
N	<u> </u>	
01 % N DAMAGE TO OFFSITE PROPERTY 04 NARRATIVE DESCRIPTION 0-4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	02 C OBSERVED (DATE: Wells	
Potential damage to groundwater con	nlamination	
01 II O CONTAMINATION OF SEWERS, STORM DRAINS, WI 04 NARRATIVE DESCRIPTION	WTPs 02 T OBSERVED (DATE.	_) = POTENTIAL = ALLEGED
<i>N</i> ,	/A	
01 THE ILLEGAL UNAUTHORIZED DUMPING 04 NARRATIVE DESCRIPTION	02 C OBSERVED IDATE.	_) I POTENTIAL I ALLEGED
N/	A	
05 DESCRIPTION OF ANY OTHER KNOWN, POTENTIAL, OR	ALLEGED MAZAROS	
N	A	
III. TOTAL POPULATION POTENTIALLY AFFECTED:		
IV. COMMENTS		
No health proble	ems have been d	ocumented
V. SOURCES OF INFORMATION GIO MORRE PROMISED & 3 MILE	SERVICE SAFFER SHOPLE SECURE	
MDNR files		